

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5A




FIG. 5B





FIG. 5C



7/17




FIGURE 6

FIG. 7A




FIG. 7B






FIG. 7C




FIG. 7D




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 13





FIG. 14



# Measured frequency switching for a 16-bit MS-MCU




FIGURE 15A

FIGURE 15B

FIG. 16




FIG. 17




FIG. 18






FIG. 19

